

Oil Field Environmental Incident Summary

Incident: 20150311092403 **Date/Time of Notice:** 03/11/2015 09:24

Responsible Party: ONEOK Rockies Midstream

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 3/10/2015 **Time Incident:** 17:00

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 102 **Sec:** 23 **Qtr:** NE SW

Location Description: Head west on County Road 16 off of Highway 85 and proceed for 2 miles. The road will then turn to the south for a mile. The road bends to the west again but head east instead. The release site is in the middle of the wheat field.

Submitted By: Mitch Anderson

Received By:

Contact Person: Mitch Anderson
2700 Lincoln Avenue SE
Sidney, MT 59270

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident Pipeline Leak

Release Contained in Dike Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	3	Barrels	3	Barrels		

Description of Other Released Contaminant:

Natural Gas Liquids (Condensates)

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards.

Areal Extent:

The entire contents released from the pipe was contained within the pipeline trench.

Potential Environmental Impacts:

There were no adverse environmental impacts associated with this pipeline strike.

Action Taken or Planned:

The pipeline leak was isolated and allowed to de-pressurize to allow for repairs to be conducted.

Wastes Disposal Location: Contaminated soil will be transported to a licensed landfill facility.

Agencies Involved:

Updates

Date: 3/11/2015

Status: Reviewed; Followup Required

Staff: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spoke with company contact via phone at 9:45. Contact said that the release was contained to the excavation and would be addressed for cleanup as soon as possible. He also mentioned that the release was in the middle of a wheat field and access was a problem at the time, but they were attempting to get equipment to the location today or tomorrow at the latest. Additional followup needed to access cleanup and document proper remediation of the area.